


SUPPLEMENTAL INFORMATION AND PHOTOGRAPHS MAY BE ADDED ON SHEET OF SAME SIZE

<p>1. STATE <b>Maryland</b>  COUNTY <b>Worcester</b>  TOWN <b>Girdletree</b> VICINITY  STREET NO. <b>Rt. 12, 1.7 miles north of</b>  <b>Girdletree</b>  ORIGINAL OWNER  ORIGINAL USE <b>dwelling</b>  PRESENT OWNER <b>Milton Barnes</b>  PRESENT USE <b>Tenant House</b>  WALL CONSTRUCTION <b>frame</b>  NO. OF STORIES <b>1</b></p>	<p style="text-align: center;">HIS <b>IC</b> AMERICAN BUILDINGS SURVEY  INVENTORY <b>WO-44</b></p> <p>2. NAME <b>Barnes House</b>    DATE OR PERIOD <b>18th century</b>  STYLE <b>Colonial</b>  ARCHITECT  BUILDER</p> <p>3. FOR LIBRARY OF CONGRESS USE</p>
<p>4. NOTABLE FEATURES, HISTORICAL SIGNIFICANCE AND DESCRIPTION <span style="float: right;">OPEN TO PUBLIC <b>NO</b></span></p> <p>The Barnes House is a very long, small, frame house that fits into the category of: "Big House, Little House, colonade and kitchen." The unique aspect of this house is that it is all one story. This house is very much like many four-part houses on the Eastern Shore of Virginia. The largest part of the building is built on a tall brick foundation. It is three bays long and two bays deep, with door located on the northern end of the three bays. The door is battened and has a four-pane transom. Windows have nine over six sash on first story and six over six in south gable. The building is sheathed with beaded clapboard and covered by an "A" roof.</p> <p>The second portion of the complex is two bays long, having a chimney on its north gable. It is also built on a brick foundation but lower than the larger portion. Windows have nine over six sash and the cornice has curved end-boards on its south ends.</p> <p>The third portion or 'hyphen' is a two bay-long, enclosed section with door and window. Finally, the kitchen is a two-bay-long, frame building with chimney at north gable. This also has a door and windows, the window in the latter two portions having six over six sash. The latter two portions also have a leanto porch on the east side.</p> <p>The building is in very poor condition and is tenanted by a large negro family.</p>	
<p>5. PHYSICAL CONDITION OF STRUCTURE    <b>Endangered</b>                      <b>Interior</b>                      <b>Exterior</b></p>	
<div style="display: flex; justify-content: space-between;"> <div style="width: 45%;"> <p>6. LOCATION MAP (Plan Optional)</p>  </div> <div style="width: 45%;"> <p>7. PHOTOGRAPH</p> </div> </div>	
<p>8. PUBLISHED SOURCES (Author, Title, Pages)  INTERVIEWS, RECORDS, PHOTOS, ETC.</p>	<p>9. NAME, ADDRESS AND TITLE OF RECORDER</p> <p style="text-align: center;"><b>Michael Bourne</b>  <b>MARYLAND HISTORICAL TRUST</b>  <b>2525 RIVA ROAD</b>  <b>ANNAPOLIS, MARYLAND 21401</b>  DATE OF RECORD <b>July, 1969</b></p>

1. STATE <u>Maryland</u> COUNTY <u>Worcester</u> TOWN <u>Girdletree</u> VICINITY STREET NO. <u>Rt 12, 1.7 miles north of</u> <u>Girdletree</u> ORIGINAL OWNER ORIGINAL USE <u>dwelling</u> PRESENT OWNER <u>Milton Barnes</u> PRESENT USE <u>tenant house</u> WALL CONSTRUCTION <u>frame</u> NO. OF STORIES <u>1</u>		HISTORIC AMERICAN BUILDINGS SURVEY INVENTORY <u>WO-44</u>	
		2. NAME <u>Barnes House</u> DATE OR PERIOD <u>18th Century</u> STYLE <u>Colonial</u> ARCHITECT BUILDER	
		3. FOR LIBRARY OF CONGRESS USE	
4. NOTABLE FEATURES, HISTORICAL SIGNIFICANCE AND DESCRIPTION OPEN TO PUBLIC <u>NO</u>			
<p>The Barnes House is a very long, small, frame house that fits into the category of: "Big House, Little House, colonade and kitchen." The unique aspect of this house is that it is all one story. This house is very much like many four-part houses on the Eastern Shore of Virginia. The largest part of the building is built on a tall brick foundation. It is three bays long and two bays deep, with door located on the northern end of the three bays. The door is battened and has a four-pane transom. Windows have nine over six sash on first story and six over six in south gable. A large irregular brick chimney is located on the south gable. The building is sheathed with beaded clapboard and covered by an "A" roof.</p> <p>The second portion of the complex is two bays long, having a chimney on its north gable. It is also built on a brick foundation, but lower than the larger portion. Windows have nine over six sash and the cornice has curved end-boards on its south ends.</p> <p>The third portion or 'hyphen' is a two-bay-long, enclosed (continued on reverse side)</p>			
5. PHYSICAL CONDITION OF STRUCTURE Endangered <u>yes</u> Interior Exterior <u>poor</u>			
6. LOCATION MAP (Plan Optional)			
7. PHOTOGRAPH			
8. PUBLISHED SOURCES (Author, Title, Pages) INTERVIEWS, RECORDS, PHOTOS, ETC.		9. NAME, ADDRESS AND TITLE OF RECORDER <u>Michael Bourne</u> <u>Maryland Historical Trust</u> DATE OF RECORD <u>July, 1969</u>	

WO-44 (continued)  
Barnes House

section with door and window. Finally, the kitchen is a two-bay-long, frame building with chimney at north gable. This also has a door and windows, the window in the latter two portions having six over six sash. The latter two portions also have a leanto porch on the east side.

The building is in very poor condition and is tenanted by a large negro family.



Barnes House

WC-44

110B



Barnes House

WO-44

moB



• JUL • 69



Barnes House

WO-44

MOB